

SOUTH PRODUCTION NOTES

Jan 23, 2016
11-7 Shift Notes

BASF EMPLOYEES

57 Last Recordable
125 Last Lost time

SAFETY Notes: Check the walkways for ice and treat with icemelt.
Need to remind operators that Styrene material on line #2 can't be washed down the drain.
Building 31 sump currently shut off.

Title V Notes: Trimer – Trimer is on ORP.
CTO – Kicked out today and needs repairs. Down for now.
Powder Room DC found with blowdowns off. Continuing blowing down. Replace the bags as soon as we can.

#1 MED / D 0713:

Continue running. Use the acid and water numbers from the change order section of the MOD.
Do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed, but is not needed for this product.

#1 RC / D 0713:

Restart calciner after New pfaudler temperature reaches 250. Currently down so we can perform the 2nd impreg on the Pfaudler.
Make sure we feed the calciner in batch order.

#2 MED line / Styrene:

Continue making batches, but do not have more than 6-7 bags on the floor ahead of the calciner.
Need to remind operators that Styrene material can't be washed down the drain.
Installed auger #28. Auger #13 is on the floor behind #2 extruder and can be used next when we need a change out about 100,000# into the run.
The new mixer plows should be in the week of the 2/29.

#2 RC/ Styrene:

Continue feeding. We are trying to run to the F1. The Floor CRT or designated person will need to take a sample out of the F1 scrubber. Before unlocking building 31 sump WWTP will test these samples for moly and if the sump is low, we can unlock and send to WWTP. At all other times the west sump will remain locked out.

Need to remind operators that Styrene material can't be washed down the drain.
The new mixer plows should be in the week of the 2/29.
We need Bag #10 checked weighed and repacked.

#3 MED line / AL 3945:

Hold off making batches, 30+ bags on the floor.
Need to remind operators to use their wet mix.
Try to keep extruder speed at 15Hz when we are running.
Please keep a close eye on the ammonia and nitric additions.

#3 RC / AL-3945:

Currently down due to issue with the CTO going out.

#4 RC / D-0222 Cleaning:

Everything has been washed out of the calciner. Syntron has been put back together.

#5 RC / Catoxid:

Out of feed. 2 bags of wet material to wait for engineering – don't feed now.
Continue to monitor 5A after filter.
The log sheet is in the 2nd floor MCC room bldg. 11 - needs to be filled out every 2 hrs.

#6 RC & Dryer / D-0761:

We can start feeding again once the calciner reaches temperature.

West Pfaudler / D 4601:

Temperature on the pfaudler was at 135 at 10PM. We should be able to start the second impregnation at the beginning of midnight shift. Will continue with last batch as priority over #1 calciner. **When 250 deg is reached while drying we can start #1 back up.**
Geredco is scheduled to come in Jan 28th to do work on the Pro ring. We will need to be down at that point.

East Pfaudler/ D-0761:

We will not be making batches until the sly scrubber is fixed and #6 is up and running.
Engineer gave the go ahead to repack the material with the small extrusions.
Was done on midnights.

6 Tank: Tank empty

Valve fixed. There was a screen and band clamp in the valve.

7 Tank: D-0226 Solution

Pumped out the solution in this tank. We have 2 totes worth on the 2nd floor to be used in the next run.

National Dryer / D-5206:

Schirmer finished soda blasting. Hold for next product.

PK Blender / Zr 0403:

Geredco will be back on Friday for more repairs. Lucas is setting up a portable heater so that we can heat up the vessel after patch is applied. Trying to target making batches on Saturday night.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down.

DC gauge has been added to the Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25.

Abbe Blender / D 5206:

HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

Tower 3 / AI 5645:

Done with testing do not need to staff

Tower 6 / AI 5645:

Done with testing do not need to staff.

Repacking in screening room:

North Screener / DPT-0101:

Room was cleaned on day shift.

South Screener / DPT-0101:

Room was cleaned on day shift.

#2662 (west) Pill Machine /

Back together and holding.

#2664 (east) Pill Machine /

Back together and holding.

TK #2 / Zr-0404:

Kiln is in the process of being lit. Need to finish lighting and bring up to temp. Mark wants to start feeding material once it comes up to temperature.

TK #4 / Cu 0203:

Feeding is complete, just need to unload.

FYI- this product contains chrome and TK area is now a regulated area. Please wear your respirators in this area.

Milling V 2046: N/A

Harrop Kiln / Al 3920:

Hold off on lighting until after the Tower trainings. Plan to start 1/25/16.

Saggers have been switched out and are ready for next run.

Building 27 Belt Filter / Cu-6081:

On hold until interlock for discharge can be implemented.

Priorities:

- 1) West Pfaudler/Trimer
- 2) East Pfaudler/#6 RC
- 3) #2 MED/RC
- 4) #3 RC/CTO
- 5) #1 MED/RC
- 6) South PK (after liner repairs are completed)
- 7) #2 Tunnel Kiln
- 8) #2 RC North
- 9) Zr-0403 T Tableting Line

Maintenance notes: New mixer plows for #2 mixer are due in the week of 2/29.